



RICHMOND EMERGENCY OPERATIONS CENTER

Thursday, January 12, 2023

EVACUEE NOTICE UPDATE

Seaview Drive Incident

RICHMOND, California – On Tuesday, January 3, 2023, at 8:18 PM, the City of Richmond Fire and Police departments responded to the 300 block of Seaview Drive on reports of a break-line in the hillside which, due to an expected weather event, had the potential to develop into a landslide. Following recent storm surges, the hillside above Seacliff Drive and Seaview Drive in the Brickyard Cove area became unstable. City staff and technical experts assessed the area. Out of an abundance of caution and due to concerns that additional storms were approaching with anticipated heavy rainfall, residents of Seaview Drive and Seacliff Way were asked to evacuate. The City of Richmond Emergency Operations Center was activated to support the incident.

To ensure their continued safety, residents, at this time, cannot return to their homes.

Temporary accommodations for evacuated residents remain available at the Hyatt Place in Emeryville and have been extended through January 23, 2023. City staff will provide updates about additional extensions of the Hyatt Place's temporary accommodations for evacuated residents if necessary.

Public Safety personnel and Emergency Operations staff will continue to monitor and secure the area. **For additional** questions or concerns, please contact the City of Richmond at EOCPIO@ci.richmond.ca.us.

###