INSTRUMENT MONITORING RECORD

BIOMAX ENVIRONMENTAL
Environmental Consulting and Industrial Hygiene Services

775 San Pablo Ave., Pinole, CA 94564

Phone: (510) 724-3100
Fax: (510) 724-3145

Project Name: Veolia Water - H_2S

Project Number: 102110-01

Job Site: Point Richmond

Date: 10/23/10

Instrument: Jerome 631-X

Model/Serial Number: 631-X / 1748

Calibration Method: Manual

Operator Name (*Print*): Michael A. Polkabla

Time/Date: 1030 10/23/10

Signature: [signature]

Slight Drizzle @ 1200 wind

Time	Reading (ppm)	T/RH	Location / Notes	
1050	0.000		Calibration / Equipment Set up - office	
1120	0.000		Site zero / calibration @ Point Richmond	
1130	0.000	69/59%	Washington Elementary School	0-5 S
1145	0.000	70/55	Veolia Water Treatment Plant @ Gate	0-10S
1150	0.000	70/56	Storm Drain @ Entry Gate Veolia	0-10S
1200	0.000	70/58	Point Richmond Tech Center / West Marine	0-10S
1220	0.000	68/61%	Mechanics Bank MH Cover	0-5S
1230	0.000	68 64%	MH @ Street W Richmond / Railroad Ave	0-5S
1315	0.000	68/69%	Fire Station Entry Location	0-5S
1330	0.000	67/68	55 Idaho Street Residence	0-5S
1345	0.000	67/69	28 Montana Street Residence	0-5S
1355	0.000	67/72	331 E Richmond Ave Residence	0-5S
1415	0.000	67/76	Send of E Richmond Ave	0-5S
1435	0.000	66/71	226 Scenic Drive East	0-5S
1450	0.000	66/72	318 Washington Street Residence	0-5S
1510	0.000	66/75	479 W. Richmond Residence	0-5S
1535	0.000	65/76	225 Contra Costa Residence	0-10S
1552	0.000	65/75	771 Ocean Ave	0-10S
1610	0.000	65/78	Point Richmond Fire Department	0-5S
1628	0.000	65/78	36 Railroad Ave @ Little Louie's	0-5S
1705	0.000	65/75	Manhole @ Mechanics Bank w/ Cover	0-5S
1720	0.000	66/77	Manhole @ SE Corner Cutting / Canal	0-5S
1735	0.000	66/78	Zero post calibration of unit @ BioMax	0-5S