

INSTRUMENT MONITORING RECORD

BIOMAX ENVIRONMENTAL

Environmental Consulting and Industrial Hygiene Services

775 San Pablo Ave., Pinole, CA 94564

Phone: (510) 724-3100

Fax: (510) 724-3145

H2S

Project Name: City of Richmond Wastewater Treatment Facility

Project Number: 102110-01

Job Site: Point Richmond

Date: 10/24/10

Instrument: Jerome 631-X

Model/Serial Number: 631-X / 1748

Calibration Method: Manual

Operator Name (Print): Michael A. Polkaba, CIH

Time/Date: 10/24/10

Signature: *Michael A. Polkaba*

Precipitation Present

| Time | Reading (ppm) | T/RH | Location / Notes |
|------|---------------|-------|---|
| 1010 | 0.000 | 70/65 | Calibration @ Biomax. NA |
| 1045 | 0.000 | 64/80 | Calibration zero @ PR. NA |
| 1058 | 0.000 | 64/82 | Washington Elementary School 10-15S |
| 1120 | 0.000 | 63/85 | Richmond Water Treatment Plant @ Gate 10-15S |
| 1135 | 0.000 | 63/88 | West Marine @ PR Tech Center 10-15S |
| 1145 | 0.000 | 63/89 | PR Tech Center Entry 10-15 |
| 1157 | 0.000 | 64/90 | PR Fire Station @ Main Doors 10-15 |
| 1210 | 0.000 | 63/88 | 55 Idcho Street Residence 10-15 |
| 1225 | 0.000 | 62/89 | 28 Montana Street Residence 10-15 |
| 1238 | 0.000 | 63/91 | 331 E. Richmond Ave Residence 10-20 |
| 1249 | 0.002 | 62/92 | S End of E. Richmond Ave 10-20 |
| 1255 | 0.001 | 62/92 | " Verification same location 10-20 |
| 1320 | 0.000 | 63/88 | 726 Scenic Drive East Residence 10-20 |
| 1346 | 0.000 | 64/89 | 318 Washington Street Residence 10-20 |
| 1359 | 0.000 | 63/91 | 479 W Richmond Residence 10-15 |
| 1415 | 0.000 | 62/92 | 225 Contra Costa St Residence 10-15 |
| 1432 | 0.000 | 62/93 | 651 Ocean Ave / Marine Ave 15-25 S |
| 1448 | 0.000 | 63/91 | 841 Ocean Ave / Residence 15-25 S |
| 1505 | 0.000 | 63/90 | Teuksbury @ Clarence St (Border near Chevron) 10-15 S |
| 1520 | 0.001 | 63/93 | Point Richmond FD at Street 5-10 N |
| 1525 | 0.000 | 63/93 | Verify Above @ PRFD 5-10 N |
| 1542 | 0.000 | 63/90 | Mechanics Bank @ Market 5-10 S |
| 1557 | 0.000 | 62/91 | Little Lowe's on RR Ave 5-10 S |
| 1645 | 0.000 | 70/69 | Post Calibration / Regen @ Biomax NA |
| | | | |
| | | | |
| | | | |
| | | | |