INSTRUMENT MONITORING RECORD

Richmond Fire Department Field Monitoring Log

BIOMAX ENVIRONMENTAL
Environmental Consulting and Industrial Hygiene Services

775 San Pablo Ave., Pinole, CA 94564

Phone: (510) 724-3100
Fax: (510) 724-3145

Location / Incident Description : Veolia Fence-line and Evaporation Ponds @ Richmond Pkwy.

Date: 1/11/2011

Instrument: H_2S Monitor Jerome 631X

Model/Serial Number: Jerome631-X 2747

Calibration Method: Standard / Field

Operator Name (*Print*): Michael A. Polkabla, CIH

Time/Date: 1945 HRs 1/11/2011

Signature: Michael A. Polkabla

Time	*Reading (ppm)*	*Wind/Dir*	*Observations / Location / Odors (+/-)*
1945	0.000	—	Zero Calibration @ Station 64 Fire House
1951	0.002	—	Fire Station w/o zero filter
2017	0.002	⊖	Fenceline @ Richmond Pkwy (RP) and Gertrude Ave (-)
2028	0.002	⊖	Fenceline @ RP and Pittsburg (-) (-)
2038	0.002	⊖	Fenceline @ RP and Gertrude Ave (-)/Parr Blvd
2056	0.003	⊖	Veolia gate @ main entrance (+)
2106	0.003	⊖	Veolia fenceline @ Nursery on Canal (+)
2115	0.002	⊖	Washington Elementary Parking Lot (-)
2132	0.002	⊖	RP and Parr Blvd Evaporation ponds (-)
2143	0.002	⊖	RP and Pittsburg Ave fenceline (-)
2154	0.002	⊖	RP and Gertrude Ave fenceline (-)
2204	0.002	⊖	Veolia main gate area (-)
2215	0.003	⊖	Veolia fenceline @ Nursery on Canal (+)
2222	0.002	⊖	Point Richmond Fire Station Downtown (-)
2231	0.002	⊖	RP and Gertrude Ave
2239	0.002	⊖	RP and Pittsburg Ave
2245	0.002	⊖	RP and Parr Blvd
2257	0.000	—	Post Calibration Equipment / site
2315	0.000	—	Post Cal Equipment @ Biomax